



Atera SIGNO

BMW
2er Coupe (F22) 03/2014-




7





8


nur bei / only for Part-No.: 045 196



9



- nur bei Art.Nr.: 045 196
only for part no.: 045 196
- | | |
|---------------|-----------------|
| A- 991970065 | 11- 9910700004 |
| B- 9945700111 | 12- 9908700010 |
| C- 9918700253 | 13- 9922700204 |
| | 14- 9918700243 |
| | 15a- 9949700742 |
| | 15b- 9949700743 |
| | 15c- 9949700743 |
| | 15d- 9949700742 |
-
- | |
|----------------|
| 1- 9945700090 |
| 2- 9919700062 |
| 3- 9945700105 |
| 4- 9912700051 |
| 5a- 9918700526 |
| 5b- 9918700527 |
| 6- 9918700250 |
| 7- 9918700249 |
| 8- 9910700004 |
| 9- 9908700231 |
| 10- 9908700222 |





10



Atera SIGNO

BMW
2er Coupe (F22) 03/2014-

Part-No. : 044 196
Part-No. : 045 196



Part-No. : 044 196



Atera
MADE IN GERMANY




Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Internet: www.atera.de



© ATERA GmbH
Ref.-Nr.: 044 196_096434419600_992570050200
Ref.-Nr.: 045 196_096434519600_992570050200
Stand/State: 01/09/2014 – Rev 00 Ver 00

Atera SIGNO

BMW
2er Coupe (F22) 03/2014-



Atera SIGNO

BMW
2er Coupe (F22) 03/2014-

